


TPS Status October 10 2013


Displacement support with screw jacks and bevel gear boxes




...and ac motor drives



Gear wheel assemblies for potentiometer position read out



Main vacuum vessel support system with position adjustment screws



Limit switch actuators and adjustable feet for vacuum vessel
Feet allow for x,y,z adjustment and permit plug n play principal for the vacuum vessel.

